

DISCLOSURES REGARDING FAITH BAPTIST CHURCH AT 509 E 56TH, HUTCHINSON, KS 67501

- Stains on basement ceiling near main stairs caused by toilet leak.
- The toilet in the men's bathroom leaks, the water has been turned off.
- Gray water from kitchen sink and from baptistry empty into a drainage pipe which takes it to east ditch on Plum St.
- The carpet in basement was removed when pump quit and underflow pipe clogged, water backed up into basement.
- No foundation or slab problems
- Some florescent lights in the basement and some in the main auditorium need to be replaced.
- 9-6-2006: New Fisher Heating & Air Conditioning for 2 Trane Natural Gas Furnaces and 2 Trane Air Conditioning Units \$9,627.71
- 5-17- 2010 – Guttering; Proposal from C & C Guttering for \$2,234.25
- 6-15-2010 – Insurance payment for roof hail damage (\$11,189.55 received from Brotherhood Mutual Insurance) Received estimates from Weichert roofing, Kropf Lumber and Wray roofing in June 2010 – Roof replaced June 1 2010.
- 3-30-2021 – Fisher Heating & Air Conditioning serviced Furnace.
- 5-13-2021 – Replaced 40 Gallon Natural gas water heater, \$950 Pd to Preferred Plumbing
- 9-5-2021 – Fisher Heating & Air serviced outdoor air conditioning units.
- 7-17-2022 – Paid - Miller Drilling for 44 Gallon Pressure tank and Switch for \$900.00
- July ²⁰²¹ ~~2021~~ – Heating and Air Conditioning Units serviced.
- July 2023 Church Inspected for Termites.